


BOCAGE OAK HERRINGBONE/CHEVRON A 90°



WOOD BE BEAUTIFUL LTD

September 27, 2023




BOCAGE OAK HERRINGBONE/CHEVRON A 90°



| REVISIONS | | |
|-----------|------------|-----------------|
| | MM/DD/YY | REMARKS |
| 1 | 27 /09 /23 | INITIAL RELEASE |
| 2 | --/--/-- | ... |
| 3 | --/--/-- | ... |
| 4 | --/--/-- | ... |
| 5 | --/--/-- | ... |

A 01



BOCAGE OAK HERRINGBONE/CHEVRON A 90°




WOOD BE BEAUTIFUL LTD

REVISIONS

| | MM/DD/YY | REMARKS |
|---|------------|-----------------|
| 1 | 27 /09 /23 | INITIAL RELEASE |
| 2 | --/--/-- | ... |
| 3 | --/--/-- | ... |
| 4 | --/--/-- | ... |
| 5 | --/--/-- | ... |

02

A



BOCAGE OAK HERRINGBONE/CHEVRON A 90°




WOOD BE BEAUTIFUL LTD

REVISIONS

| | MM/DD/YY | REMARKS |
|---|------------|-----------------|
| 1 | 27 /09 /23 | INITIAL RELEASE |
| 2 | --/--/-- | ... |
| 3 | --/--/-- | ... |
| 4 | --/--/-- | ... |
| 5 | --/--/-- | ... |

03

A



Angle of cut on y plane 90° +/- 2°
 Angle de coupe sur plan y 90° +/- 2°

BOCAGE OAK HERRINGBONE/CHEVRON A 90°



WOOD BE BEAUTIFUL LTD

REVISIONS

| | MM/DD/YY | REMARKS |
|---|------------|-----------------|
| 1 | 27 /09 /23 | INITIAL RELEASE |
| 2 | --/--/-- | ... |
| 3 | --/--/-- | ... |
| 4 | --/--/-- | ... |
| 5 | --/--/-- | ... |

04

A